

HISTORIC AMERICAN ENGINEERING RECORD

HAER
MD,
1-CUMB,
1-

INDEX TO PHOTOGRAPHS

Baltimore and Ohio Railroad:
Queen City Hotel & Station
Cumberland
Allegany County
Maryland

HAER No. MD-4

NOTE: Photographs were taken by William E. Barrett, photographer, 1970

- MD-4-1 VIEW OF CENTER CUPOLA FROM SOUTH WING
- MD-4-2 PROFILE VIEW AT CORNICE LEVEL OF FRONT OF HOTEL LOOKING NORTH
- MD-4-3 VIEW OF FOUR BAYS AT NORTH ELEVATION
- MD-4-4 VIEW OF ATTIC AREA IN NORTH WING SHOWING STRUCTURAL SYSTEM
 (Photo taken in March 1971)
- MD-4-5 VIEW OF WOODEN SPIRAL STAIRCASE LEADING TO CUPOLA
 (Photo taken in March 1971)
- MD-4-6 VIEW OF APEX OF ROOF TRUSS IN NORTH WING
 (Photo taken in March 1971)
- MD-4-7 INTERIOR VIEW OF FIREPLACE AND WINDOW IN THIRD FLOOR ROOM
- MD-4-8 VIEW OF CORNER ROOM SHOWING DOOR TO BATH
- MD-4-9 DETAIL VIEWS OF STAIR BALUSTRADE ON LANDING BETWEEN SECOND AND
 THIRD FLOOR, NORTH END
- MD-4-10 VIEW OF MAIN ENTRY DOOR
- MD-4-11 VIEW LOOKING SOUTH AT BALLROOM ON GROUND FLOOR
- MD-4-12 DETAIL VIEW OF CAST-IRON TRELLISWORK
- MD-4-13 PHOTOGRAPH OF DEMOLITION IN PROGRESS
- MD-4-14 PHOTOGRAPH OF DEMOLITION IN PROGRESS
- MD-4-15 VIEW OF MOUNTAINS OF RUBBLE FOLLOWING DEMOLITION
- MD-4-16 VIEW OF FORMER PASSENGER PLATFORMS AND CANOPIES WITH DEMOLISHED
 STATION-HOTEL IN BACKGROUND
- MD-4-17 DEMOLITION IN PROGRESS

Baltimore and Ohio Railroad:
Queen City Hotel and Station
HAER No. MD-4
Index to Photographs
(Page 2)

MD-4-18	VIEW OF FRONT FACADE FROM ELEVATED HIGHWAY DURING DEMOLITION
MD-4-19	VIEW OF FRONT FACADE FROM ELEVATED HIGHWAY BEFORE DEMOLITION
MD-4-20	VIEW OF FRONT FACADE FROM BUILDING SHOWING CAST-IRON TRELLISWORK ON PORCHES
MD-4-21	DETAIL VIEW OF WOODEN FRAMING IN UPPER PART OF CUPOLA
MD-4-22	VIEW OF TOP FLOOR CORRIDOR, WEST SIDE
MD-4-23	DETAIL VIEW OF MAIN FLOOR LOBBY
MD-4-24	REAR VIEW, EAST SIDE UNDER NEW ELEVATED HIGHWAY
MD-4-25	VIEW OF LAUNDRY ROOM ON LOWER LEVEL SHOWING LARGE BRICK FIREPLACE
MD-4-26	3/4 VIEW OF NORTHERN END OF BUILDING AND TRACKSIDE ELEVATIONS
MD-4-27	VIEW OF BUILDING LOOKING SOUTHWEST FROM ROOFTOP OF MONTGOMERY WARD STORE ACROSS TRACKS (Photo taken in March 1971)
MD-4-28	VIEW OF TRACKSIDE (WEST) ELEVATION
MD-4-29	VIEW OF TRACKSIDE (WEST) ELEVATION DURING DEMOLITION (Photo taken in March 1971)
MD-4-30	DETAIL VIEW OF CAST IRON WINDOW HOOD MOLDING
MD-4-31	3/4 VIEW OF WEST ELEVATION DURING DEMOLITION, LOOKING NORTHEAST
MD-4-32	VIEW OF CENTER PORTION OF BUILDING AFTER DEMOLITION, LOOKING SOUTHEAST
MD-4-33	VIEW OF CENTER PORTION OF BUILDING AFTER DEMOLITION, LOOKING NORTHEAST
MD-4-34	VIEW OF CENTER PORTION OF BUILDING AFTER DEMOLITION, WITH ONLY BACK WALL STANDING
MD-4-35	AERIAL VIEW OF STATION AND VICINITY, LOOKING SOUTH
MD-4-36	AERIAL VIEWS OF STATION AND VICINITY, LOOKING EAST